


Are there SPIKES on current from HV-PS to Drawers?

= NO ?

1) Box for HV current was adapted to BNO instead of SHV connectors



2) No spikes. GT. 1.5 mA was seen during AC current measurement
DC current measurement corresponds to value given by HV PS.

3) Spikes at level up to 65 mA were seen when MV was switched ON pictures above

4) Noise were seen at levels {0.85/1.0/0.85/0.4/0.3/0.25} mA for Drawers {1/2/3/4/5/6}