





A JUMPER SHOULD BE MADE BETWEEN VCC IN ON S-LINK CONNECTOR J4 COMP SIDE AND S-LINK CONNECTOR J5 SOLDER SIDE, FOR CURRENT MEASUREMENTS.

REF: SLIBOX.LOGIC.1.1	TITLE: SLINK CONNECT BOX	
CERN CN/CE DIV. ECP EDU/DQ 1211 GENEVA 23 SWITZERLAND	ABBREV: SLIBOX REV 1 11 - 6 - 96	PAGE: 1
	DESSIN: A. VAN PRAAG / ETUDE:	DATE: 21-11-95