

Last update 18.6.2002

HVS1 Power Supplies for TILECAL Detector Table of Crate Deployment

serial number	current location	HW repair	SW repair	comment prototype
00 001	Tesla	Done		
01 001	FZU	Done	Done	
01 002	FZU	Done	Done	
01 003	CERN hala modulu Blg. 185	Done		
01 004	FZU	Done		
01 005	C-F			
01 006	CERN placed into rack, testbeam zone H8			
01 007	FZU	Done		
01 008	FZU	Done	Done	
01 009	C-F			
01 010	FZU	Done		
01 011	FZU	Done		
01 012	FZU	Done		
01 013	CERN czech room Blg. 188			
01 014	FZU	Done		
01 015	FZU	Done		
01 016	FZU	Done		
01 017	FZU	Done		

HW repair: New level (full load) overvoltage
SW repair: change ROM memory (new SW construction)